

OJT WORK PROCESS SCHEDULE (A)

OUTSIDE PLANT (OSP) INSTALLER

O*NET #: DOT: #821.261-014 AIMS#:0282

<i>Description</i>	<i>Approximate Hours</i>
A. Installation of Cable Plant Installation of buried cable, buried wires, coax cable and fiber optic; aerial cable, drops, poles, guys and anchors; buried load coils and cable route markers; station protection, pedestal and terminals; inside wiring and station equipment; splicing cables, records and material.	3,500
B. Testing Testing cable troubles; splicing of buried and aerial plants; inside station wire troubles; subscriber station equipment; and outside plant facilities.	500
C. Maintenance Maintenance of cable troubles; splicing of buried and aerial cable plant; inside station wire troubles; subscriber station equipment; buildings and grounds; warehousing/supply' shop areas, assigned vehicles, and construction equipment; records and reports.	4,000
Total Hours	<hr/> 8,000